


Distributor Spark Advance Curve 430 cid Motor



		Distributor Spark Advance	
Engine rpm	Distrib 1/2 rpm	Current	Factory
500	250	0	0
750	375	0	1
1000	500	2	6
1250	625	8	13
1500	750	22	17
2000	1000	28	22
2500	1250	28	25
3000	1500	32	27
3500	1750	34	27
4000	2000	42	28
Vacuum Max 7 deg			